

From: ["Stuesse, Gregory L." <stuessegl@cdmsmith.com>](mailto:stuessegl@cdmsmith.com)

To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:sheldrake.sean@epa.gov)

["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)

CC: ["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:scott.coffey@cdmsmith.com)

[madi.novak@state.or.us](mailto:madi.novak@state.or.us)

[Sarah.GREENFIELD@state.or.us](mailto:Sarah.GREENFIELD@state.or.us)

["Greazel, Andrew" <GreazelAD@cdmsmith.com>](mailto:GreazelAD@cdmsmith.com)

["lrby-Smith, Karen" <lrbySmithKE@cdmsmith.com>](mailto:lrby-smith@cdmsmith.com)

Date: 5/22/2018 10:01:04 AM

Subject: Daily Report for Monday 5/21/18 Portland Harbor Pre-RD Investigation - Surface Sediment Sampling

Attachments: [Daily Status Report\\_Portland Harbor\\_20180521\\_SurfaceSed.docx](#)

---

Sean and Davis,

Attached is the daily report for Monday 5/21/18 which includes oversight of the surface sediment sampling on the Cayuse and Tieton. Light sheen was noted at SG-S221-1 and SG-S222-3, and a moderate sheen was observed on SG-B298-4. No sheen was observed in the Willamette River. All sampling equipment was decontaminated per the FSP. All soil and rinsate were contained separately and taken to AECOM's storage building.

Please contact me if you have any questions.

Thanks, Greg

Greg Stuesse, PE, LG | Senior Project Manager | CDM Smith

14432 SE Eastgate Way, Suite 100 | Bellevue, WA 98007

Main: 425.519.8300 | Direct: 425.519.8358 | Cell: 206-715-6752

[stuessegl@cdmsmith.com](mailto:stuessegl@cdmsmith.com) | <mailto:stuessegl@cdmsmith.com%7C> [www.cdmsmith.com](http://www.cdmsmith.com) <<http://www.cdmsmith.com>>